

Product discontinuation notification (PDN)

Title / short description Discontinuation due to portfolio streamlining
Affected article category Terminal blocks
Change category Discontinuation
Change number IBE190018-00
Reason for PCN/PDN Revision

Purpose/objective of the change

Discontinuation due to portfolio streamlining

Detailed description of the change

Discontinuation for strategic reasons with replacement item

Identifying characteristics

See attached item list for discontinued items

Start of Production (SOP)	-	Last Time Delivery (LTD)	2024-05-30
Effective date (EOP)	2024-02-29	End of Service (EOSR)	-
End of Sales (EOS)	2024-02-29		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IBE190018-00 Abkündigung aufgrund einer Portfoliobereinigung_DE
- PDN-IBE190018-00 Discontinuation due to portfolio streamlining_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1401019	MBK			3248025	MUT 1,5
1414006	MBK 2,5/E			3248030	MUT 2,5
1414019	MBK 2,5/E BU			3248031	MUT 2,5 BU
1402788	MBK 2,5/E-PE			3248032	MUT 2,5-PE
1413010	MBK 3			3248030	MUT 2,5
1413094	MBK 3 BU			3248031	MUT 2,5 BU
1413036	MBK 3/E-Z			3248030	MUT 2,5
1413078	MBK 3/E-Z BU			3248031	MUT 2,5 BU
1413117	MBK 3/E-Z-PE			3248032	MUT 2,5-PE
1415018	MBK 5			3248035	MUT 4
1415092	MBK 5 BU			3248036	MUT 4 BU
1415076	MBK 5/E			3248035	MUT 4
1415115	MBK 5/E BU			3248036	MUT 4 BU
1415089	MBK 5/E-TG			-	-
1402940	MBK 5/E-Z			3248035	MUT 4
1402982	MBK 5/E-Z BU			3248036	MUT 4 BU
0452043	MBK 5/E-Z -PE			3248037	MUT 4-PE
1402092	MBK 10 BU			3248038	MUT 6
1401093	MBK BU			3248026	MUT 1,5 BU
1402225	ATS-MBK			1413227	ATP-MBK
1414035	D-MBK 2,5/E			3248033	D-MUT 2,5/4
1414022	D-MBK 2,5/E BU			3248034	D-MUT 2,5/4 BU
1413023	D-MBK 3/5			3248033	D-MUT 2,5/4
1413104	D-MBK 3/5 BU			3248034	D-MUT 2,5/4 BU
1413706	D-MBK 5/E-T			3248033	D-MUT 2,5/4
1413049	D-MBK 6/E			3248033	D-MUT 2,5/4
1415021	D-MBK/E			3248033	D-MUT 2,5/4
1415102	D-MBK/E BU			3248034	D-MUT 2,5/4 BU
1418073	MBK 5/E-FS			-	-
1418112	MBK 5/E-FS BU			-	-
1417074	MBK 5/E-FS/FS			-	-
1407013	MBK-FS			-	-
1407097	MBK-FS BU			-	-
1406014	MBK-FS/FS			-	-
1406098	MBK-FS/FS BU			-	-
0452027	MSLKG 2,5			3248032	MUT 2,5-PE
0552024	MBK 6/E			3248038	MUT 6
1402018	MBK 10			3248038	MUT 6

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
0452014	MSLKG 5			3248037	MUT 4-PE
0801791	TP-BK/MBK			-	-
1410505	MSLKG 6			3248040	MUT 6-PE