

June 9, 2023

PTN

Withdrawal of PTC thermistors

To streamline the product range, the following EPCOS PTC thermistors (temperature sensors, overcurrent protection components, heating elements and motor-start PTCs) are being withdrawn. For alternative parts that are not listed, please contact your regional sales contact.

Affected products

Ordering code	Substitute type
B59001J1130B040	
B59011C1040A070	
B59011U0180B010	
B59015R1190B040	
B59016R1190B040	
B59018U0220B010	
B59022A1080B010	
B59022A1080B062	
B59039D7201U010	
B59053A0110A010	
B59053A0150A010	
B59053A0175B010	
B59053A0180A010	
B59053A0220A010	
B59054A0210B120	
B59067A0100B010	
B59076S1120B054	
B59088U1055B070	
B59093A0080B110	
B59096R0100B010	
B59098C1100B055	
B59100C0080A054	B59100C0080A070
B59100C0090A070	
B59100C0100A051	
B59107R0090B010	
B59123A0130B010	
B59123U0130B010	
B59131R0130B010	
B59141R0140B010	
B59141R0180B010	
B59141S1170B010	
B59142S1150B010	

TDK Electronics AG

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany
 Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250
 Chairman of the Supervisory Board: Dr. Werner Faber
 Management Board: Dr. Werner Lohwasser, Chairman · Juergen Holzinger · Joachim Thiele
www.tdk-electronics.tdk.com

PPD
Thermistors
 Internal / External

230609PPD1e

June 9, 2023

Ordering code	Substitute type
B59142U0120B054	
B59160A0140A010	
B59174R0160B010	
B59185S1120B054	
B59193A0120A020	
B59193R0270B110	
B59196R0130B010	
B59199A0120A020	
B59202J0135B010	
B59205R0140B210	
B59205R0140B310	
B59206R0140B010	
B59225J0140A020	
B59248B1080B153	
B59274U0160B053	
B59288R0190B010	
B59290R0155B010	
B59290R0180B010	
B59294R0170B010	
B59302R0140B210	
B59326R0140B010	
B59339A1201P020	
B59340R0150B010	
B59356R0180B010	
B59356R0195B010	
B59360R0180B010	
B59370R0240B010	
B59389R0140B010	
B59391R0120B010	
B59404A0130A062	
B59414R0220B010	
B59415U0160B010	
B59514R0150B010	
B59673A0100B010	
B59701A0110A162	
B59811C0135A070	
B59841C0135A070	
B59860C0120A554	
B59860C0120A570	
B59861C0135A051	
B59870C0120A470	B59870C0120A070
B59873C0120A052	

June 9, 2023

Ordering code	Substitute type
B59874C0120A051	B59874C0120A070
B59875C0120A051	B59875C0120A070
B59875U1120B051	
B59880C0120A054	B59880C0120A070
B59881C0135A070	
B59883C0120A370	B59883C0120A070
B59884C0120A054	
B59885C0120A054	B59885C0120A070
B59890C0080A054	B59890C0080A070
B59890C0120A054	B59890C0120A070
B59910C0120A070	
B59915C0120A070	
B59930C0160A051	
B59935C0120A051	B59935C0120A070
B59945C0120A051	B59945C0120A070
B59955C0120A051	B59955C0120A070
B59960C0160A070	
B59970C0080A051	B59970C0080A070
B59970C0160A051	B59970C0160A070
B59980C0160A070	
B59985C0160A051	B59985C0160A070
B59990C0160A070	B59990C0160A051
B59995C0160A051	B59995C0160A070

Deadline for last orders: September 22, 2023

Last shipments by: December 22, 2023

Contact Libor Hojka, KT PPD BA PM, Kutina

Customers are asked to address inquiries directly to their sales contacts.

June 9 2023

Withdrawal of PTC thermistors

Affected Parts List

B59202J135B10V60
B59960C160A70Z15
B59202J135B10V60
B59910C120A70Z15
B59915C120A70Z15
B59811C135A70Z15
B59884C120A54Z15
B59960C160A70Z15
B59202J135B10V60
B59404A130A62
B59404A130A62
B59053A180A10V60
B59339A1201P20Z5
B59811C135A70Z15
B59841C135A70Z15
B59884C120A54Z15
B59910C120A70Z15
B59915C120A70Z15