

## Product discontinuation notification (PDN)

<b>Title / short description</b>	Abkündigung von Produkten und Produktvarianten "old UK"
<b>Affected article category</b>	Terminal blocks
<b>Change category</b>	Discontinuation
<b>Change number</b>	IBE190019-01
<b>Reason for PCN/PDN Revision</b>	Korrektur der Artikelliste

---

### Purpose/objective of the change

Discontinuation due to portfolio streamlining

### Detailed description of the change

Discontinuation due to (partial) availability of alternative products

### Identifying characteristics

See attached item list for discontinued items

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	2025-01-31
<b>Effective date (EOP)</b>	2024-10-31	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	2024-10-31		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

---

### Attachments

- Material\_list.csv
- PDN-IBE190019-01\_DE
- PDN-IBE190019-01\_EN

## Material list

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
3058018	AP-RSC-KS			3058017	AP RSC
0810012	BSLK 16			3044173	UT 10-PE
3057144	UDK 3 RD			3044542	UT 2,5-QUATTRO
3003174	UK 2,5 N/RS			3044076	UT 2,5
3002018	UK 3			3044076	UT 2,5
3002092	UK 3 BU			3044089	UT 2,5 BU
0531210	UK 4-EX BKYE-FE			3047617	UT 4-FE
3004456	UK 10-EX ALTER FUSS			3044160	UT 10
3005028	UK 10-PR			1054163	UT 10 P/P
3006179	UK 16 N-PE/N			3044199	UT 16
3059016	UK 16-PR			1054163	UT 10 P/P
3048315	UK 35 BK			3044226	UT 35 BK
3048328	UK 35 RD			3044227	UT 35 RD
3048219	UK 35-FE			3047676	UT 35-FE
3008009	UK 35-IB			3047727	UT 35 IB
3048072	UK 35-IB BU			3047730	UT 35 IB BU
3048154	UK 35-IB-FE			3047727	UT 35 IB
5022290	SLK 4 O.SOCKEL U. FEDER			3044128	UT 4-PE
0524997	SLK 35-EX			0523998	SLK 16-EX
0270018	USK 4-FSR(4-2,8-0,8)			2017237	UHK 4-FS(8-2,8-0,8)
0271017	USK 4-FS/FS(8-2,8-0,8)			2017224	UHK 4-FS/FS(12-2,8-0,8)
0442011	USLKG 10			3044157	UT 6-PE
0442082	USLKG 10 N-1			3044173	UT 10-PE
0442024	USLKG 10-1			3044157	UT 6-PE
0443010	USLKG 16			3044173	UT 10-PE
0443036	USLKG 16 N-1			3044212	UT 16-PE
0448015	USLKG 16-1			3044173	UT 10-PE
0449014	USLKG 35-1			3044241	UT 35-PE
0444035	USLKG 35-IB			3044241	UT 35-PE
0441517	USLKG 5-1			3044128	UT 4-PE
0444048	USLKG 6 N-1			3044157	UT 6-PE
2780014	UXKK 4			3044814	UTT B 4
0201605	ZS-6				
2701574	GE 10/2-BA BU				
5031003	ST-K 4 ASEA				
2770066	TS-U3K 2,5				
3008054	UK 35-PE/N				
0443081	USLKG 2,5 N-1				

Item no.	Item Type	Hardware / Firmware old	new	Item no.	Substitute item Type
0444020	USLKG 35 BK				