

Product discontinuation notification (PDN)

Title / short description Discontinuation of the MSB/MSDB/MSBV product family
Affected article category Terminal blocks
Change category Discontinuation
Change number IBE210013-00
Reason for PCN/PDN Revision

Purpose/objective of the change
 Discontinuation

Detailed description of the change
 Discontinuation due to portfolio streamlining

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-03-31
Effective date (EOP)	2024-12-31	End of Service (EOSR)	-
End of Sales (EOS)	2024-12-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IBE210013-00_DE
- PDN-IBE210013-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
3244012	MSB 2,5	00	00	1073602	MPT 2,5-NS 15
3244025	MSB 2,5 BU			1073605	MPT 2,5-NS 15 BU
3244151	MSB 2,5-PE			1073761	MPT 2,5-NS 15-PE
3244041	MSB 2,5-F			3249010	D-MPT 2,5-F
3244054	MSB 2,5-F BU			3249010	D-MPT 2,5-F
3244067	MSB 2,5-M			3249005	MPT 2,5-M
3244070	MSB 2,5-M BU			3249006	MPT 2,5-M BU
3244264	MSB 2,5-FE-M			3249007	MPT 2,5-M-FE
3244096	MSB 2,5-M OG			3249005	MPT 2,5-M
3244106	MSB 2,5-M YE			3249005	MPT 2,5-M
3244119	MSB 2,5-NS 35			1073553	MPT 2,5-NS 35
3244122	MSB 2,5-NS 35 BU			1073554	MPT 2,5-NS 35 BU
3244135	MSB 2,5-NS 35 OG			1073553	MPT 2,5-NS 35
3244148	MSB 2,5-NS 35-PE			1073555	MPT 2,5-NS 35-PE
3244149	MSB 2,5-NS 35-PE BD:PE			1073555	MPT 2,5-NS 35-PE
3244164	MSB 2,5-RZ			3249011	MPT 2,5-RZ
3244177	MSB 2,5-RZ BU			3249012	MPT 2,5-RZ BU
3244165	MSB 2,5-FE-RZ			1073762	MPT 2,5-RZ-FE
3244203	MSB 2,5-RZ YE			3249011	MPT 2,5-RZ
3249017	MSBV 2,5			1073602	MPT 2,5-NS 15
3249020	MSBV 2,5 BU			1073605	MPT 2,5-NS 15 BU
3249059	MSBV 2,5-F			3249010	D-MPT 2,5-F
3073238	MSBV 2,5-M OG			3249005	MPT 2,5-M
3249088	MSBV 2,5-NS 35			1073553	MPT 2,5-NS 35
3244216	MSDB 2,5			1429436	MPTD 2,5-NS 15
3244229	MSDB 2,5 BU			1429437	MPTD 2,5-NS 15 BU
3244232	MSDB 2,5-F			3249010	D-MPT 2,5-F
3244245	MSDB 2,5-F BU			3249010	D-MPT 2,5-F
3244263	MSDB 2,5-FE-F			3249010	D-MPT 2,5-F
3244262	MSDB 2,5-FE-M			1429432	MPTD 2,5-M-FE
3244340	MSDB 2,5-FE-RZ			1429443	MPTD 2,5-RZ-FE
3244258	MSDB 2,5-M			1429280	MPTD 2,5-M
3244261	MSDB 2,5-M BU			1429430	MPTD 2,5-M BU
3244287	MSDB 2,5-M OG			1429433	MPTD 2,5-M OG
3244290	MSDB 2,5-M YE			1429434	MPTD 2,5-M YE
3244300	MSDB 2,5-NS 35			1429438	MPTD 2,5-NS 35
3244326	MSDB 2,5-NS 35 OG			1429438	MPTD 2,5-NS 35
3073131	MSDB 2,5-NS 35 YE			1429438	MPTD 2,5-NS 35

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
3244339	MSDB 2,5-RZ			1429441	MPTD 2,5-RZ
3244342	MSDB 2,5-RZ BU			1429442	MPTD 2,5-RZ BU
3244371	MSDB 2,5-RZ YE			1429441	MPTD 2,5-RZ
3249185	MSDBV 2,5-F BU			3249010	D-MPT 2,5-F
3249208	MSDBV 2,5-M BU			1429430	MPTD 2,5-M BU
3073241	MSDBV 2,5-M YE			1429434	MPTD 2,5-M YE
3249211	MSDBV 2,5-NS 35			1429438	MPTD 2,5-NS 35
3073212	MSDBV 2,5-NS 35 OG			1429438	MPTD 2,5-NS 35
3024180	D-MSB 1,5-F			3249010	D-MPT 2,5-F
3024193	D-MZB 1,5-NS35			3249019	D-MPT 2,5-RZ
3024177	D-MZB 1,5			3249019	D-MPT 2,5-RZ
3251018	D-MSBV 2,5			3249019	D-MPT 2,5-RZ
3251021	D-MSBV 2,5-F			3249010	D-MPT 2,5-F
3029703	ESB 2-MZDB			3030161	FBS 2-5
3244193	MSB 2,5-RZ OG			3249011	MPT 2,5-RZ
3073102	MSDB 2,5 OG			1429436	MPTD 2,5-NS 15
3073115	MSDB 2,5 YE			1429436	MPTD 2,5-NS 15
3244313	MSDB 2,5-NS 35 BU			1429439	MPTD 2,5-NS 35 BU
3244368	MSDB 2,5-RZ OG			1429441	MPTD 2,5-RZ
3249143	MSDBV 2,5			1429436	MPTD 2,5-NS 15
3249156	MSDBV 2,5 BU			1429437	MPTD 2,5-NS 15 BU
3249172	MSDBV 2,5-F			3249010	D-MPT 2,5-F
3249198	MSDBV 2,5-M			1429280	MPTD 2,5-M
3249224	MSDBV 2,5-NS 35 BU			1429439	MPTD 2,5-NS 35 BU