

Product discontinuation notification (PDN)

Title / short description Discontinuation of various products
Affected article category PCB terminal blocks and PCB connectors
Change category Discontinuation
Change number IAA230005-
Reason for PCN/PDN Revision

Purpose/objective of the change

Discontinuation of connection elements for flexible PCBs

Detailed description of the change

We aim to provide you with state-of-the-art products for your application. It is therefore necessary to phase out some components from time to time for commercial or technical reasons.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-04-01
Effective date (EOP)	2024-10-01	End of Service (EOSR)	-
End of Sales (EOS)	2024-10-01		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IAA230005-_DE
- PDN-IAA230005-_EN

Material list

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
1010317	PTF 0,3/ 2-WB-8-H PC4001 L500				
1014846	PTF 0,3/ 4-BB-8 WH BLT				
1025894	PTF 0,3/ 4-BB-10-H KP				
1038668	PTF 0,3/ 4-BB-8-H SL				
1063804	PTF 0,3/ 2-WB-8-H OS SET 1PC				
1098594	PTF 0,5/ 2-WB-8-HPC0140L250V1				
1098596	PTF 0,5/ 2-WB-8-HPC0140L2000V1				
1098599	PTF 0,3/ 4-BB-8-H V1				
1184156	PTF 0,3/ 2-WB-8-H PC4001PL50_1				
1184159	PTF 0,3/ 4-WB-10-H PC1234P L50				
1267180	PTF 0,3/ 4-BB-8-H SL KP				
1280179	PTF 0,3/ 2-WB-8-H PC0140L300KP				
1280182	PTF 0,5/ 2-WB-8-H PC0410L500KP				
1280183	PTF 0,5/ 2-WB-8HPC0410L2000KP				
1707558	PTF 0,3/ 2-WB-8-H				
1707559	PTF 0,3/ 4-BB-8-H				
1707561	PTF 0,3/ 4-WB-8-H				
1707562	PTF 0,3/ 2-WB-10-H				
1707563	PTF 0,3/ 4-BB-10-H				
1707565	PTF 0,3/ 4-WB-10-H				
1710165	PTF 0,3/ 2-WB-8-H L1000-OS				
1710167	PTF 0,3/ 2-WB-8-H-OS				
1710168	PTF 0,3/ 2-WB-8-H-PC IP54-OS				
1710169	PTF 0,3/ 4-BB-8-H-OS				
1710170	PTF 0,3/ 4-WB-8-H-L1000-OS				
1710171	PTF 0,3/ 4-WB-8-H-OS				
1711691	PTF 0,3/ 2-WB-8-H PC4001P L50				
1711693	PTF 0,3/ 2-WB-8-HPSC4001PL1000				
1711694	PTF 0,3/ 2-WB-8-H SC4001 L2000				
1711696	PTF 0,3/ 2-WB-8-H C4001 L500				
1713318	PTF 0,5/ 2-WB-8-H PC0410L500				
1713319	PTF 0,5/ 2-WB-8-H PC0410L2000				
1713645	PTF 0,3/ 2-WB-10-H PC4001L500				
1713878	PTF 0,5/ 3-WB-8-HPC6501L500 OS				
1713900	PTF 0,3/ 2-WB-8-HPC0410500BOS				
1714995	PTF 0,3/ 4-WB-10-H PC1234L150				
1715071	PTF 0,5/ 3-WB-8-HPC1056L500OS1				
1715570	PTF 0,3/ 2-WB-8-H PC0140L1200				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
1715753	PTF 0,3/ 2-WB-8-H PC0140PL60				
1715785	PTF 0,3/ 2-WB-8-H PC0140 L300				
1716046	PTF 0,3/ 4-WB-10-H PC2134 L150				
1820097	PTF 0,3/ 4-BB-PC IP54-OS				
1848477	PTF 0,3/ 4-FLEX-I-8				
1848480	PTF 0,3/ 4-FLEX-L-8				
1848493	PTF 0,3/ 4-FLEX-T-8				
1848503	PTF 0,3/ 4-FLEX-I-10				
1848516	PTF 0,3/ 4-FLEX-L-10				
1848529	PTF 0,3/ 4-FLEX-T-10				
1864011	PTF 0,3/ 4-WB-8-H PCP 40				