

**Product Change Notification** 

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

1. ECN #: 233201

2. Date of Announcement: July 16, 2014

#### 3. Series:

• TFM - .050 X .050 MICRO STRIPS

#### 4. Part #'s Affected


• TFM-1XX-XX-X-DH-XX

# 5. Description of Change:

Weld tab aperture size and spacing is being changed to prevent solder paste from being printed off of the board.

# 6. Method of Identifying Change

Corrected stencils will not allow solder paste to print past the edge of the board.



#### 7. Reason for Change:

This is a change to the stencil design only. The PCB footprint will remain as is.

### 8. Impact of Change on Form, Fit, or Function:

- Fit The spacing and size of the weld tab apertures are being changed.
- 9. Projected Implementation Date: October 09, 2014