



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631 www.littelfuse.com

October 28th, 2014

Product Change Notification for Radial Varistor MPQ, MDQ and MOQ (PCN# 4080E)

Dear Valued Customers,

Littelfuse would like to notify you of a change relating to the Minimum Packing Quantity (MPQ), Minimum Delivery Quantity (MDQ) and Minimum Order Quantity (MOQ) for radial varistors. There will be no changes to the electrical or dimensional specification.

This change will be effective from December 1st, 2014; during this transition period, customers are expected to receive the parts in two kinds of minimum packing quantity until existing inventory in Littelfuse warehouse and the distribution channels are consumed completely.

Affected Part Number Listing:



Affected Part
Number Listing.xls



20141028 MPQ MDQ
MOQ Change for Vari

Please respond to us by November 15th, 2014 to acknowledge notification of this change. If we do not hear from you then we will expect that this change has been accepted and no further action is required. Thank you.

Best Regards
Johnny Chang
Global Product Manager
Littelfuse, Inc.
Tel: +1 773 628 0603
www.littelfuse.com