



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 242181

2. Date of Announcement: January 28, 2015

3. Series:

- FMPS - FLEX MATE MINI POWER SOCKET ASSEMBLY

4. Part #'s Affected


- SEE BELOW

5. Description of Change:

Added voids to improve end wall toe-in condition.

6. Method of Identifying Change

Old product does not have voids in the end walls. New product has obvious voids in the end walls.



7. Reason for Change:

Effort to improve historical end wall condition. Added voids allow more margin to prevent stubbing with mated half.

8. Impact of Change on Form, Fit, or Function:

- Form - Added voids in end walls

9. Projected Implementation Date: March 01, 2015