



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 265941

2. Date of Announcement: February 04, 2016

3. Series:

- RF178 - RF CABLE ASSEMBLY

4. Part #'s Affected

- RF178-03SPX-XXXXX-XXXX
- RF178-XXXXX-03SPX-XXXX

5. Description of Change:

The heat shrink length is being increased from 15.24±2.50 to 20.00±2.50 on MMCX straight plug end options.

6. Method of Identifying Change

The heat shrink will measure 20.00±2.50 instead of 15.24±2.50.

7. Reason for Change:

When the cable assembly is bent, the heat shrink reduces the severity of the bend near the ground crimp area. By lengthening the heat shrink, the bend severity is further reduced in this area thus improving the reliability of the ground connection.

8. Impact of Change on Form, Fit, or Function:

- Form - The heat shrink length is extended.
- Function - The cable assembly will be less flexible in the heat shrink area.

9. Projected Implementation Date: March 07, 2016