



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 268434

2. Date of Announcement: March 08, 2016

3. Series:

- MPC - MPC

4. Part #'s Affected



- MPC-X-XX-X

5. Description of Change:

A rib is being added to the void core area on the mating side of the part.

6. Method of Identifying Change

The new bodies will contain a new rib inside of the void core area.



7. Reason for Change:

This change is for a molding process improvement which reduces scrap during manufacturing.

8. Impact of Change on Form, Fit, or Function:

- Form - Form only

9. Projected Implementation Date: April 03, 2016