



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 272753

2. Date of Announcement: May 31, 2016

3. Series:

- HDMR - HDMR FLANGED SURFACE MOUNT SOCKET

4. Part #'s Affected

- HDMR-19-XX-X-SM-XX-XX



5. Description of Change:

Change assembly method from manual assembly to insert molding process.


6. Method of Identifying Change

Insert molding process assemblies have minor visual difference compared to the manually assembled product. Remove protrusions on shield;


1. Structure comparison



2. Front view




3. Right view



Without difference

4. Left view



Without difference

<p>5. Back view</p>	<p>6. Top view</p>
<p>7. Bottom view</p>	<p>8. Remove protrusions on shields</p>
<p>7. Reason for Change: Insert molding process improves manufacturability when compared to the manual assembly process.</p>	
<p>8. Impact of Change on Form, Fit, or Function:</p> <ul style="list-style-type: none"> Form - housing and shields have minor cosmetic differences. 	
<p>9. Projected Implementation Date: June 18, 2016</p>	