



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 279234

2. Date of Announcement: August 05, 2016

3. Series:

- LPHS - LPHS ASSEMBLY
- ET60S - ET60S SOCKET POWER ASSEMBLY
- HSEC8 - .8mm HIGH SPEED, DUAL VERTICAL MOUNT, EDGE CARD ASSEMBLY

4. Part #'s Affected


- LPHS-XX-XX-S-VXX-XX
- HSEC8-1XX-XX-S-PV-X-X-XX
- ET60S-XX-XX-XX-S-VXX-GP

5. Description of Change:

Adding PPE connector lubricant to -S plating to aid with high mating/unmating forces.

6. Method of Identifying Change

The lubricant can be detected under a UV light source.



The lubricant is shown on the top row under the UV light source. The bottom strip is not lubricated.

7. Reason for Change:

The lubricant will reduce the mating and unmating forces. All other mechanical and electrical characteristics have been tested and are not changed.

8. Impact of Change on Form, Fit, or Function:

- Function - Reduction in mating/unmating forces

9. Projected Implementation Date: August 29, 2016