



520 Park East Blvd., New Albany, IN 47150 U.S.A  
(812)-944-6733 / 1-800-SAMTEC9

## Product Change Notification

**1. ECN #:** 278088

**2. Date of Announcement:** August 05, 2016

**3. Series:**

- FHP - .156 HI POWER SOCKET ASSEMBLY

**4. Part #'s Affected**

- FHP-XX-XX-XX-S-XX-XX-XX

**5. Description of Change:**

Footprint updated to center tails on pads for surface mount FHP

**6. Method of Identifying Change**

PCBs with pads updated to match this footprint revision will have alignment pin holes offset from pad pattern by .009".

**7. Reason for Change:**

For customer to design PCB layout more effectively and to reduce confusion regarding tail-pad offset.

**8. Impact of Change on Form, Fit, or Function:**

- Fit - Tails will be centered on pads using this revision of footprint layout
- Form - Pad pattern centerline will be visibly offset from alignment pin pattern centerline.

**9. Projected Implementation Date:** September 04, 2016