



520 Park East Blvd., New Albany, IN 47150 U.S.A  
(812)-944-6733 / 1-800-SAMTEC9

## Product Change Notification

**1. ECN #:** 285091

**2. Date of Announcement:** October 24, 2016

**3. Series:**

- IPBS - .165 DOUBLE ROW SOCKET ASSEMBLY

**4. Part #'s Affected**


- IPBS-106-XX-XX-D-XX
- IPBS-107-XX-XX-D-XX
- IPBS-108-XX-XX-D-XX
- IPBS-109-XX-XX-D-XX
- IPBS-110-XX-XX-D-XX
- IPBS-111-XX-XX-D-XX
- IPBS-112-XX-XX-D-XX
- IPBS-113-XX-XX-D-XX
- IPBS-114-XX-XX-D-XX
- IPBS-115-XX-XX-D-XX



**5. Description of Change:**

Add void corings on 06 through 15 positions body.

**6. Method of Identifying Change**

Visual inspection; voids will be noticed on ends of body where prior revisions had no voids; this is a rolling change.





**7. Reason for Change:**

Changes made to improve dimensional consistency.

**8. Impact of Change on Form, Fit, or Function:**

- Form - this is a Form change.

**9. Projected Implementation Date:** November 17, 2016