

Product change information (PCN)

| | | | |
|----------|---------------------|-------|------------|
| PCN No.: | AAC170047 | Date: | 23.07.2018 |
| Product: | BC17,8 BC53,6 BC107 | | |


| Order No. | Designation |
|-----------|---------------------------|
| | See attached product list |

| Description of change | | |
|--|---|--|
| <input checked="" type="checkbox"/> Product appearance (fit) | <input checked="" type="checkbox"/> Product geometry (form) | <input type="checkbox"/> Product function (function) |

Change to the transparent BC cover

The formation of bubbles and sink marks have been identified in the area of the thicker sections on the transparent cover of the BC housing. As a permanent solution to the identified fault characteristics, the thicker sections have been thinned and redesigned.

No other product features are affected by this change.



| | |
|---|------------|
| Expected initial delivery of the changed products | 2019-01-01 |
|---|------------|