



Issue Date: March 25th, 2020
By: Julio Sanchez
Associate Product Manager
jcsanchez@littelfuse.com

Type of Notification: HBC product line – Sourcing Issue

Description:

The products in HBC line will be blocked temporarily due to component source issue. Littelfuse won't be accepting new orders for now until new notice.

Product Affected:

Part Description	Part Number
ACS HOLDER 803 500V	80300000105
ACS HLDER 823 250V	82300000005

Please contact your local LF sales person with any questions or requests.