

# PCN - Product Change Notification

<b>No.:</b>	TR-19108_G19-09320
<b>Date:</b>	22.01.2020
<b>Originator:</b>	B. Meier
<b>Subject:</b>	<b>JFA J300 receptacle contact</b> current product will be changed to SPOT gold-plated product

<b>Related product:</b>		<b>REPLACEMENT</b>		
	<b>part no.</b>	<b>description</b>	<b>description</b>	<b>part no.</b>
	382205-00	SF3F-41GF-P2.0	SF3F-41GFA-P2.0	382177-00
	382220-00	SF3F-71GF-P2.0	SF3F-71GFA-P2.0	382181-00
	382202-00	SF3F-01GI-P2.0	SF3F-01GIA-P2.0	382176-00
	382207-00	SF3F-41GI-P2.0	SF3F-41GIA-P2.0	382178-00
	382210-00	SF3F-002GF-P2.0	SF3F-002GFA-P2.0	382179-00
	382315-00	BF3F-71GF-P2.0	BF3F-71GFA-P2.0	382291-00
	382305-00	LF3F-41GF-P2.0	LF3F-41GFA-P2.0	382287-00
	382212-00	SF3F-002GI-P2.0	SF3F-002GIA-P2.0	382180-00
	382222-00	SF3F-71GI-P2.0	SF3F-71GIA-P2.0	382182-00
	382200-00	SF3F-01GF-P2.0	SF3F-01GFA-P2.0	382175-00
	382300-00	BF3F-01GF-P2.0	BF3F-01GFA-P2.0	382285-00

<b>Description of change:</b>	<p>We decided to provide a lineup of the product which is controlled the price increase while maintaining the performance by applying gold-plated to a required thickness at the important area.</p> <p>Therefore, please consider switching from the current product to the spot gold-plated product.</p> <p>The product performance is equivalent to that of the current part.</p>
-------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Identification of change:</b>	<p>Addition of "A" to the part description: e.g. SF3F-41GF-P2.0 =&gt; SF3F-41GFA-P2.0</p>
----------------------------------	-----------------------------------------------------------------------------------------------

<b>schedule:</b>	step by step
------------------	--------------

<b>Reason of change:</b>	It is difficult to maintain the current price due to the recent shortage of the material and increase in cost.
--------------------------	----------------------------------------------------------------------------------------------------------------