

Product discontinuation notification (PDN)

Title / short description	Discontinuation
Affected article category	Terminal blocks
Change category	Discontinuation
Change number	IBE200008-1

Purpose/objective of the change

Discontinuation of the Barrier-BT family

Detailed description of the change

The Barrier (BT) product line developed specifically for the East Asian market will be discontinued for strategic market reasons. There is no 100% equivalent in the PHOENIX Contact product range. Many other terminal blocks, however, are available as alternatives in the push-in, screw, or bolt connection connection technologies. Get in touch with your sales contact for more information.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2021-12-31
Effective date (EOP)	2021-11-30	End of Service (EOSR)	-
End of Sales (EOS)	2021-11-30		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IBE200008-1 Abkündigung_DE
- PDN-IBE200008-1 Discontinuation_EN

Material list

Item	Article Type	Hardware old	Firmware new	Item	Substitute item Type
3281221	AP-BTO 38				
3281103	BT 1,25-F				
3281176	BT 14				
3281179	BT 14-F				
3281110	BT 2,0-F				
3281117	BT 3,5-F				
3281133	BT 5,5				
3281136	BT 5,5-F				
3281104	BTH 1,25-F				
3281111	BTH 2,0-F				
3281118	BTH 3,5-F				
1012513	BTO 1,25-F				
3281182	BTO 14				
3281185	BTO 14-F				
1012514	BTO 2,0-F				
1012515	BTO 3,5-F				
3281200	BTO 38				
3281208	BTO 38-3L-F				
3281211	BTO 38-4L-F				
3281205	BTO 38-F				
3281139	BTO 5,5				
3281142	BTO 5,5-F				
3281105	BTP 1,25-F				
3281112	BTP 2,0-F				
3281119	BTP 3,5-F				
3281188	D-BT 14				
3281191	D-BT 14-F				
3281145	D-BT 5,5				
3281148	D-BT 5,5-F				
3281216	D-BTO 38				
3281218	D-BTO 38-F				
3281116	BTP 3,5				
3281101	BTH 1,25				
3281100	BTO 1,25				
3281129	D-BT 1,25 GY				
3281107	BTO 2,0				
3281120	D-BT 1,25				
3281121	D-BT 3,5				

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
3281128	BTP 3,5 GY				
3281108	BTH 2,0				
3281102	BTP 1,25				
3281130	D-BT 3,5 GY				
3281123	BT 2,0				
1012516	D-BT 1,25-F				
3281114	BTO 3,5				
3281113	BTP 2,0 GY				
3281106	BTP 1,25 GY				
3281122	BT 1,25				
1012627	D-BT 3,5-F				
3281109	BTP 2,0				
3281124	BT 3,5				
3281125	AP-BTO 1,25				
3281127	AP-BTO 3,5				