



Expertise Applied | Answers Delivered

8755 W. Higgins Road Suite  
500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

November 17th, 2016

To: Valued Customer

From: Littelfuse Product Management

Subject: **Snap mount holder 344-348 Series**

Littelfuse Product Management would like to inform you with regards that as Jan 9<sup>th</sup>, 2017, we will make obsolete the parts: 03440854ZX010, 344862-010, 344865-020, 344864-010 and 344865-010. We recommended using 03480870Z as alternative


Additional due lack of interest the certifications were dropped for the 344 and 348 series; because of that all the marking logos will be remove from the body and packing labels.

There are no changes in form, fit, function, or materials to our part. The changes are the elimination of the UL and CSA logos and from the holder's plastic body.


Affected part numbers:

03440601Z	03440802Z	03480671Z
03440602Z	03440803Z	03480677Z
03440603Z	03440804Z	03480871Z
03440604Z	03440805Z	03480877X
03440605Z	03480670Z	03480877Z
03440801Z	03480870Z	

**344/348 Series - Current version**



**344/348 Series – Updated version**



Please contact your local Littelfuse Sales Office should you need further assistance.

Best regards,

Aurora Contreras

Assistant Product Manager for Holders, Blocks and Clips product Line

[www.littelfuse.com](http://www.littelfuse.com)