

Product change notification (PCN)

Title / short description	Removal of EX marking for MBK 2,5-E and others
Affected article category	Terminal blocks
Change category	Marking, Documentation
Change number	CBE220046-00
Reason for PCN/PDN Revision	

Purpose/objective of the change
Discontinuation of EX certification

Detailed description of the change

Due to the discontinuation of EX certification, the explosion protection marking will be removed from the items.

Identifying characteristics
Increased production batch

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2023-01-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PCN-CBE220046-00 Entfernung der EX-Kennzeichnung MBK 2,5-E und weitere_DE
- PCN-CBE220046-00 Removal of EX marking for MBK 2,5-E and others_EN

Material list

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
1414006	MBK 2,5/E	06	07		
0452027	MSLKG 2,5	07	08		
0452014	MSLKG 5	07	08		
1923021	UK 5-TWIN	06	07		
2715982	IAK 16	05	06		