

# Product change notification (PCN)

<b>Title / short description</b>	Digital assembly instructions
<b>Affected article category</b>	Electronic housing
<b>Change category</b>	Documentation
<b>Change number</b>	CAC220059-00
<b>Reason for PCN/PDN Revision</b>	

## Purpose/objective of the change

Environmental protection, packing slips

## Detailed description of the change

We strive to avoid generating unnecessary waste, both in terms of packaging and package contents. Therefore, in the future, the packing slips will only be available digitally, with a QR code printed on the labels. A hardcopy of the packing slip will no longer be included.

## Identifying characteristics

Label

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	-
<b>Effective date (EOP)</b>	2023-09-01	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	-		

## Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

## Attachments

- Material\_list.csv
- PCN-CAC220059-00 Digitale Montageanleitung\_DE
- PCN-CAC220059-00 Digital assembly instructions\_EN

### Material list

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
2200072	BC 161,6 UT HBUS FS BK VPE80	3			
2896267	BC 71,6 UT HBUS BK	2			
2278500	BC 161,6 UT HBUS BK	2			
2896403	BC 53,6 UT HBUS BK	2			
2896254	BC 35,6 UT HBUS BK	2			
2896270	BC 107,6 UT HBUS BK	2			
2200120	BC 17,8 UT HBUS FS BK	1			
2202752	BC 161,6 SET ECO-VST	1			
2203815	BC 107,6 UT HBUS BK W/ORG CLP	1			
2201385	BC 161,6 SET ECO-CPU	1			
2896241	BC 17,8 UT HBUS BK	1			
2202951	BC 107,6 UT HBUS KMGY	0			
2202064	BC 107,6 UT HBUS BK S726	0			
2202081	BC 17,8 SET BK S2-R	0			
2202083	BC 17,8 SET BK J1-R	0			
2202082	BC 17,8 SET BK S1-R	0			
2203411	BC 107,6 UT HBUS BK S996	0			
1131299	BC 17,8 SET BK DR1-R S1410	0			
1050448	BC 71,6 UT HBUS BU5015 VPE160	0			
1385674	BC 107,6 UT HBUS GY7021	0			
2203299	BC 107,6 OT U11 SET S984	0			
1089833	BC 107,6 OT/UT U11 SET S1324	0			
1131303	BC 17,8 SET BK S1-R S1412	0			
2202976	BC 161,6 U11 SET KMGY IO1500	0			
1461391	BC 107,6 UT HBUS BK S1761	0			
2202080	BC 17,8 SET BK D1-R	0			
2203517	BC 107,6 UT HBUS KMGY/RD	0			
2201070	BC 17,8 UT HBUS KMGY	0			
1202967	BC 161,6 SET KMGY S1522	0			
1252987	BC 161,6 UT HBUS WH	0			
1131300	BC 17,8 SET BK S2-R S1411	0			
1210716	BC 53,6 UT HBUS KMGY	0			
1227345	BC 161,6 UT HBUS KMGY	0			
2202138	BC 35,6 UT HBUS BK R-IM	0			
1016021	BC 53,6 UT HBUS KMGY/RD	0			
1227344	BC 71,6 UT HBUS KMGY	0			
1018093	BC 161,6 UT HBUS BK W/ORG CLP	0			
1461394	BC 161,6 UT HBUS BK S1764	0			

Item no.	Item Type	Hardware / Firmware old	new	Item no.	Substitute item Type
1227343	BC 35,6 UT HBUS KMGY	0			