

Product change notification (PCN)

Title / short description	Revision of snap-in locking
Affected article category	PCB terminal blocks and PCB connectors
Change category	Form and appearance
Change number	CAA180059-
Reason for PCN/PDN Revision	

Purpose/objective of the change

Revision of snap-in locking

Detailed description of the change

To optimize the production process, the snap-in locking of the listed items is being revised. There are geometric changes as a result.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2024-07-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- 01639799-00 PTSM 0,5 ..-PL KUNDENZEICHNUNG ALT-NEU.pdf
- Material_list.csv
- PCN-CAA180059-_DE
- PCN-CAA180059-_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1709442	PTSM 0,5/ 2-PL-2,5 BK	01	02		
1709457	PTSM 0,5/ 2-PL-2,5 WH	01	02		
1709443	PTSM 0,5/ 3-PL-2,5 BK	01	02		
1709459	PTSM 0,5/ 3-PL-2,5 WH	01	02		
1709444	PTSM 0,5/ 4-PL-2,5 BK	01	02		
1709460	PTSM 0,5/ 4-PL-2,5 WH	01	02		
1187201	PTSM 0,5/ 4-PL-2,5 WH BD:1-4	00	01		
1236769	PTSM 0,5/ 4-PL-2,5 WH BDRD	00	01		
1217261	PTSM 0,5/ 4-PL-2,5 WHBSOG-BN	00	01		
1709446	PTSM 0,5/ 5-PL-2,5 BK	01	02		
1709462	PTSM 0,5/ 5-PL-2,5 WH	01	02		
1009483	PTSM 0,5/ 5-PL-2,5 WH/BK SET1	01	02		
1709447	PTSM 0,5/ 6-PL-2,5 BK	01	02		
1709463	PTSM 0,5/ 6-PL-2,5 WH	01	02		
1709448	PTSM 0,5/ 7-PL-2,5 BK	01	02		
1709464	PTSM 0,5/ 7-PL-2,5 WH	01	02		
1709449	PTSM 0,5/ 8-PL-2,5 BK	01	02		
1709465	PTSM 0,5/ 8-PL-2,5 WH	01	02		