

Product discontinuation notification (PDN)

| | |
|------------------------------------|----------------------------------------|
| Title / short description | Discontinuation of HDFK(V) series |
| Affected article category | PCB terminal blocks and PCB connectors |
| Change category | Discontinuation |
| Change number | IAA240002-00 |
| Reason for PCN/PDN Revision | |

Purpose/objective of the change

Discontinuation of the HDFK(V) series

Detailed description of the change

We aim to provide you with state-of-the-art products for your application. It is therefore necessary to phase out some components from time to time for commercial or technical reasons.

This correspondence is therefore notice of the discontinuation of the HDFK(V) series panel feed-through terminal blocks.

Alternative items are available in the UW(V) series. The technical performance data of these items is the same or better. The sizes and the cutout are different.

For a comparison of the series, refer to the comparison drawings in the attachment.

If you need a customer-specific version, such as printed items or color versions, please contact us.

Thank you for your understanding and we look forward to continuing our successful cooperation.

Identifying characteristics

Discontinuation

| | | | |
|----------------------------------|------------|---------------------------------|------------|
| Start of Production (SOP) | - | Last Time Delivery (LTD) | 2025-01-31 |
| Effective date (EOP) | 2024-09-02 | End of Service (EOSR) | - |
| End of Sales (EOS) | 2024-08-30 | | |

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|-----------------------------------------------------|---------------------------------------------------------------------|--------------------------------------------------------|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input checked="" type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Article_list_HDFK(V).xlsx
- HDFK vs UW 4.pdf
- HDFK vs UW 10.pdf
- HDFK vs UW 16.pdf
- HDFK vs UW 25.pdf
- HDFK vs UW 50.pdf
- HDFK vs UW 95.pdf

- Material_list.csv
- PDN-IAA240002-00_DE
- PDN-IAA240002-00_EN

Material list

| Item no. | Item Type | Hardware / Firmware | | Item no. | Substitute item Type |
|----------|----------------|---------------------|-----|----------|----------------------|
| | | old | new | | |
| 0707073 | HDFK 10 | | | 3073322 | UW 10 |
| 0709754 | HDFK 10/Z | | | 3073335 | UW 10/S |
| 0709110 | HDFK 10-VP | | | 3073461 | UW 10-POT |
| 0717050 | HDFK 10-VP/Z | | | 3073474 | UW 10-POT/S |
| 3001721 | HDFK 16 | | | 3073348 | UW 16 |
| 0717377 | HDFK 16/Z | | | 3073351 | UW 16/S |
| 0709796 | HDFK 16-VP | | | 3073487 | UW 16-POT |
| 0717063 | HDFK 16-VP/Z | | | 3073490 | UW 16-POT/S |
| 0707743 | HDFK 25 | | | 3073364 | UW 25 |
| 0717351 | HDFK 25/Z | | | 3073377 | UW 25/S |
| 0709136 | HDFK 25-VP | | | 3073500 | UW 25-POT |
| 0711205 | HDFK 25-VP/Z | | | 3073513 | UW 25-POT/S |
| 0707086 | HDFK 4 | | | 3073306 | UW 4 |
| 0714011 | HDFK 4/Z | | | 3073319 | UW 4/S |
| 0708739 | HDFK 50 | | | 1713709 | UW 50/S |
| 0705017 | HDFK 50/Z | | | 1713709 | UW 50/S |
| 0709123 | HDFK 50-VP | | | 1713843 | UW 50-POT/S |
| 0711218 | HDFK 50-VP/Z | | | 1713843 | UW 50-POT/S |
| 0709534 | HDFK 95 | | | 1713223 | UW 95/S |
| 0717364 | HDFK 95/Z | | | 1713223 | UW 95/S |
| 0714037 | HDFK 95-F/Z | | | 1713225 | UW 95-F/S |
| 0709644 | HDFK 95-F | | | 1713225 | UW 95-F/S |
| 0717979 | HDFK 95-VP | | | 1713242 | UW 95-POT/S |
| 0709916 | HDFK 95-F-VP | | | 1713243 | UW 95-POT-F/S |
| 0717076 | HDFK 95-F-VP/Z | | | 1713243 | UW 95-POT-F/S |
| 0709013 | HDFKV 10 | | | 3073403 | UWV 10 |
| 0714053 | HDFKV 10/Z | | | 3073416 | UWV 10/S |
| 0708946 | HDFKV 10-VP | | | 3073526 | UWV 10-POT |
| 0714134 | HDFKV 10-VP/Z | | | 3073539 | UWV 10-POT/S |
| 3001734 | HDFKV 16 | | | 3073419 | UWV 16 |
| 0714079 | HDFKV 16/Z | | | 3073432 | UWV 16/S |
| 0709783 | HDFKV 16-VP | | | 3073542 | UWV 16-POT |
| 0714147 | HDFKV 16-VP/Z | | | 3073555 | UWV 16-POT/S |
| 0709039 | HDFKV 25 | | | 3073445 | UWV 25 |
| 0714082 | HDFKV 25/Z | | | 3073458 | UWV 25/S |
| 0708962 | HDFKV 25-VP | | | 3073568 | UWV 25-POT |
| 0714150 | HDFKV 25-VP/Z | | | 3073571 | UWV 25-POT/S |
| 0709026 | HDFKV 4 | | | 3073380 | UWV 4 |

| Item no. | Item Type | Hardware / Firmware | | Item no. | Substitute item Type |
|----------|---------------------------|---------------------|-----|----------|----------------------|
| | | old | new | | |
| 0714040 | HDFKV 4/Z | | | 3073393 | UWV 4/S |
| 0714095 | HDFKV 50/Z | | | 1713711 | UWV 50/S |
| 0708522 | HDFKV 50 | | | 1713711 | UWV 50/S |
| 0708580 | HDFKV 50-VP | | | 1713845 | UWV 50-POT/S |
| 0717212 | HDFKV 50-VP/Z | | | 1713845 | UWV 50-POT/S |
| 0714105 | HDFKV 95/Z | | | 1713226 | UWV 95/S |
| 0709547 | HDFKV 95 | | | 1713226 | UWV 95/S |
| 0714118 | HDFKV 95-F/Z | | | 1713227 | UWV 95-F/S |
| 0709673 | HDFKV 95-F | | | 1713227 | UWV 95-F/S |
| 0717089 | DP-HDFK 10/5,5 | | | | |
| 0717092 | DP-HDFK 16/5,5 | | | | |
| 0709893 | DP-HDFK 25/10,9 | | | | |
| 0709990 | DP-HDFK 50/7,2 | | | | |
| 0717102 | DP-HDFK 95/15 | | | | |
| 0714024 | HDFK 10-HV/Z | | | | |
| 0706650 | HDFK 4 BK | | | | |
| 3213234 | HDFK 4 BLOCK 5GY-1GN | | | | |
| 0707866 | HDFK 4 GNYE | | | | |
| 3076646 | HDFK 10 BU | | | | |
| 0707879 | HDFK 10 GNYE | | | | |
| 0709615 | HDFK 10 NZ462008.0158.00 | | | | |
| 0709741 | HDFK 10 NZ578690 TA | | | | |
| 0709738 | HDFK 10 NZ578708 TA | | | | |
| 0707824 | HDFK 10A | | | | |
| 0709602 | HDFK 10A GNYE | | | | |
| 0717746 | HDFK 10A NZ.A5E00703412 | | | | |
| 0717814 | HDFK 10A NZA5E00859456 | | | | |
| 0709864 | HDFK 10-HV | | | | |
| 3001265 | HDFK 10-HV GNYE | | | | |
| 1161865 | HDFK 10-HV/ 3 BK | | | | |
| 0707840 | HDFK 10I | | | | |
| 0717306 | HDFK 10I NZ | | | | |
| 0709440 | HDFK 10I NZ572743 | | | | |
| 0709453 | HDFK 10I NZ572891 | | | | |
| 0717775 | HDFK 10I-AMK | | | | |
| 1712242 | HDFK 10I-AMK T10L | | | | |
| 0709372 | HDFK 10I-VP DICHTPLATTE | | | | |
| 0709385 | HDFK 10I-VP VERGUSSPLATTE | | | | |
| 0709194 | HDFK 10-VP GNYE | | | | |

| Item no. | Item Type | Hardware / Firmware | | Item no. | Substitute item Type |
|----------|-------------------------------|---------------------|-----|----------|----------------------|
| | | old | new | | |
| 0717393 | HDFK 10-VP-HV | | | | |
| 0714558 | HDFK 10-VP-HV/Z | | | | |
| 0709880 | HDFK 16 A | | | | |
| 0709877 | HDFK 16 GNYE | | | | |
| 0716093 | HDFK 16 I-VP VERGUSSPLATTE | | | | |
| 0717539 | HDFK 16-VP GNYE | | | | |
| 0707769 | HDFK 25 GNYE | | | | |
| 0717034 | HDFK 25 MIT.SCHRAUBE SIX LOBE | | | | |
| 0708276 | HDFK 25A | | | | |
| 1712252 | HDFK 25I-AMK T25L | | | | |
| 0717542 | HDFK 25-IB | | | | |
| 0709356 | HDFK 25I-VP DICHTPLATTE | | | | |
| 0707785 | HDFK 25-PE | | | | |
| 0709149 | HDFK 25-VP GNYE | | | | |
| 0717335 | HDFK 25-VP SLS/Z | | | | |
| 0711221 | HDFK 25-VP/Z GNYE | | | | |
| 0717610 | HDFK 50 A/Z OHNE METALL | | | | |
| 1708275 | HDFK 50 BU | | | | |
| 0708726 | HDFK 50 GNYE | | | | |
| 0717607 | HDFK 50 METALL | | | | |
| 0711328 | HDFK 50A-IB | | | | |
| 0708713 | HDFK 50-DP | | | | |
| 0709932 | HDFK 50I | | | | |
| 0709411 | HDFK 50I NZ.572867 | | | | |
| 0717843 | HDFK 50I NZ.A5E00913046 | | | | |
| 0717830 | HDFK 50I NZ.A5E00913073 | | | | |
| 3026214 | HDFK 50-IB | | | | |
| 3026227 | HDFK 50-IB GNYE | | | | |
| 3072611 | HDFK 50-IB/Z | | | | |
| 0709343 | HDFK 50I-VP VERGUSSPLATTE | | | | |
| 0708991 | HDFK 50-VP GNYE | | | | |
| 1828015 | HDFK 50-VP/2/VK OHNE METALL | | | | |
| 1828028 | HDFK 50-VP/3/VK OHNE METALL | | | | |
| 1068676 | HDFK 50-VP/Z BK | | | | |
| 1068678 | HDFK 50-VP/Z BU | | | | |
| 0711234 | HDFK 50-VP/Z GNYE | | | | |
| 1711258 | HDFK 50-VP/Z IB/WS | | | | |
| 1068679 | HDFK 50-VP/Z RD | | | | |
| 1864587 | HDFK 50-VP/Z-IB/IB | | | | |

| Item no. | Item Type | Hardware / Firmware | | Item no. | Substitute item Type |
|----------|-----------------------------|---------------------|-----|----------|----------------------|
| | | old | new | | |
| 0717186 | HDFK 50-VP-IB | | | | |
| 3072624 | HDFK 50-VP-IB GNYE | | | | |
| 0710840 | HDFK 50-VP-IB OHNE SCHRAUBE | | | | |
| 3246560 | HDFK 50-VP-IB/IB | | | | |
| 0711098 | HDFK 95A | | | | |
| 0717513 | HDFK 95A MIT LOCH | | | | |
| 0717490 | HDFK 95A-F O.METALL | | | | |
| 0710808 | HDFK 95-F-A | | | | |
| 0717665 | HDFK 95-F-VP GNYE | | | | |
| 0711247 | HDFK 95-F-VP OHNE SCHRAUBE | | | | |
| 0717500 | HDFK 95-F-VP TEILBE 2 | | | | |
| 0710811 | HDFK 95-F-VP TEILBEST. | | | | |
| 0710798 | HDFK 95I-VP VERGUSSPLATTE | | | | |
| 0714066 | HDFKV 10-HV/Z | | | | |
| 0709275 | HDFKV 4 GNYE | | | | |
| 0709291 | HDFKV 10 GNYE | | | | |
| 0711357 | HDFKV 10A | | | | |
| 1712307 | HDFKV 10A T10L | | | | |
| 0717238 | HDFKV 10-HV | | | | |
| 0717254 | HDFKV 10-VP-HV | | | | |
| 0714561 | HDFKV 10-VP-HV/Z | | | | |
| 0717694 | HDFKV 16 BK | | | | |
| 0717704 | HDFKV 16 BU | | | | |
| 0709770 | HDFKV 16 GNYE | | | | |
| 0717681 | HDFKV 16 RD | | | | |
| 0717856 | HDFKV 16-VP BU | | | | |
| 0709903 | HDFKV 16-VP GNYE | | | | |
| 0709042 | HDFKV 25 GNYE | | | | |
| 0717762 | HDFKV 25A | | | | |
| 1712304 | HDFKV 25A T25L | | | | |
| 1032735 | HDFKV 4/ 4 BD:1-4 | | | | |
| 1032737 | HDFKV 4/12 BD:1-12 | | | | |
| 0708548 | HDFKV 50 GNYE | | | | |
| 1712332 | HDFKV 50 T25L | | | | |
| 0709929 | HDFKV 50A | | | | |
| 0708797 | HDFKV 50-VP GNYE | | | | |
| 0717225 | HDFKV 50-VP IB/Z | | | | |
| 0717474 | HDFKV 50-VP-IB/IB | | | | |
| 1712235 | HDFKV 95 T45 | | | | |

| Item no. | Item Type | Hardware / Firmware | | Item no. | Substitute item Type |
|----------|---------------|---------------------|-----|----------|----------------------|
| | | old | new | | |
| 0717717 | HDFKV 95-F-A | | | | |
| 0717720 | HDFKV 95-F-VP | | | | |