





## Change Notification

Messrs. \_\_\_\_\_

No. C2M1CXS- \_\_\_\_\_

Issue Date : Jan. 9, 2015

Company Name : Murata Manufacturing Co., Ltd.

Approved by 	Issued by 
--	--

Department : High performance power device dept.

We are implementing the following change. Please be informed:

Product Description	Your Part No.	
	Murata Part No.	DMF3R5R5L334M3DTA0
Reason for Change : (x) Design ( ) Manufacturing Process ( ) Manufacturing Method ( ) Equipment ( ) Outgoing Inspection Method ( ) Manufacturing Location ( ) Other ( )		
Reason Details: We change the marking on product and its package label in order to receive the safety standard (UL 810A) certification.		
Contents of change		
Current Product Marking : No company name Label Marking: No UL mark	After Change Product Marking : Company name is added. Capacitance and ESR value codes are deleted. Label Marking: UL mark and capacitance value are added.	Influence to Product Characteristics etc.  No influence
For details, please see attached PDF file "Appendix 1, Details of change"		
Scheduled Date of Change : From production in February, 2015		

G1F068-01A (Y5)