

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

2. Date of Announcement: September 08, 2016

Product Change Notification

3. Series:

• SEAM - SEAM .050 PITCH TERMINAL ARRAY ASSEMBLY

4. Part #'s Affected

1. ECN #: 282522

- SEAM-XX-06.5-XX-XX-X-A-XX-K-TR
- SEAM-XX-07.0-XX-XX-X-A-XX-K-TR
- SEAM-XX-09.0-XX-XX-X-A-XX-K-TR
- SEAM-XX-11.0-XX-XX-X-A-XX-K-TR
- SEAM-XX-13.0-XX-XX-X-A-XX-K-TR

5. Description of Change:

Increasing the size of the kapton dot for the elevated SEAM series.

6. Method of Identifying Change

The SEAM elevated parts are those with lead styles: -06.5, -07.0, -09.0, -11.0, and -13.0. For these lead styles and the following row options, the Kapton has increased in diameter as follows: 4 row has changed from .236 to .256, the 5 and 6 row has changed from .236 to .325, the 8 row has changed from .325 to .404, the 10 row has changed from .404 to .460.

7. Reason for Change:

The larger K DOT will be more capable for holding the heavier elevated SEAM parts.

8. Impact of Change on Form, Fit, or Function:

- Form the dot will be noticeably larger for the elevated parts.
- 9. Projected Implementation Date: October 04, 2016