



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Subject: Notice of Obsolescence – LFPSM Series Fuse Holders For 10x38 Midget Style Fuses

Document# LFPCN_PG0095

Date: 02/26/2018

This letter is to inform Littelfuse Sales, Sales Support & Customers of the discontinuation of Littelfuse LFPSM Series Fuse Holders to consolidate our offering. The change will allow us to focus our attention and strengthen our inventory position on our legacy LPSM Series Holders which are an alternative to the LFPSM Series and significantly more popular with customers. This change is effective immediately. Inventory is still available for most LFPSM part numbers and will be available for sale until our inventory has been exhausted. Below is a cross-ref table to the alternative LPSM series. Please review its [datasheet](#) on our website for your application's specific requirements. I apologize for any inconveniences this change may cause.

Discontinued Part Numbers	Alternative Part Numbers
LFPSM0001Z	LPSM0001Z
LFPSM0002Z	LPSM0002Z
LFPSM0003Z	LPSM0003Z
LFPSM0004Z	LPSM0004Z
LFPSM0001ZXID	LPSM0001ZXID
LFPSM0002ZXID	LPSM0002ZXID
LFPSM0003ZXID	LPSM0003ZXID
LFPSM0004ZXID	LPSM0004ZXID

If you have any questions, please contact a Littelfuse representative.

Regards,



Expertise Applied | Answers Delivered

Jim McGuire

Assistant Product Manager

Industrial Business Unit

Littelfuse, Inc.

Tel: +1 773-628-0708

Fax: +1 773-830-1797

www.littelfuse.com/industrial