

Product Change Notification & Product Discontinuation Notification [PCN & PDN]

Manufacturer master data	
Company short name: Phoenix Contact	
Title / short description: Discontinuation of 93G and 93H products	
Type of notification: Product discontinuation notification	Issue date: 2019-4-9 Document ID: IAB190007
PCN format version: VDMA24903_1.0	Document Revision: 01
Company name: PHOENIX CONTACT GmbH & Co. KG	
Street: Flachsmarktstraße 8	Contact type: MANUFACTURER
ZIP code: 32825	Business Unit: Field Device Connectors (FDC)
City: Blomberg	E-Mail: info@phoenixcontact.com
State: North-Rhine Westphalia	Country: DE

Cause of change

Phoenix Contact Product Category

- Connectors

Item category by VDMA 24903

- Connectors/cables

Item change type by VDMA 24903

- Discontinuation

Item change type by smartPCN

Group

Description of change

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- Software / Firmware Bugfix
- Short-term delivery stop by supplier
- Short-term recall by supplier
- Force majeure
- Product improvement with customer benefits
- Others

Others:

Discontinuation with replacement products

Life cycle data

Effective date (PCN) / End of production (PDN) - EOP

2019-11-30

Description of change

Technical description – purpose

Discontinuation of the RJ45 patch cable products with cables 93G and 93H.

Technical description – detail

An optimized cable portfolio has led to 93G cables being superseded by 93B cables and 93H cables being superseded by 93C cables. Replacements for the discontinued products are therefore available without a transitional period.

Identifying characteristics

Replacement of 93G cables with 93B cables and replacement of 93H cables with 93C cables.

Attachments

- Material_list.csv
- IAB190007_DE.pdf
- IAB190007_EN.pdf

Material list			
Item	Revision status		Substitute item
	Hardware/Firmware OLD	Hardware/ Firmware NEW	
1411868 NBC-R4AC- EC4/.../...	02		1411857 NBC-R4AC- PN4/.../...
1411869 NBC-R4ACR- EC4/.../...	02		1411858 NBC-R4ACR- PN4/.../...
1411870 NBC-R4AC- R4AC-EC4/.../...	02		1411861 NBC-R4AC- R4AC-PN4/.../...
1411871 NBC-R4AC- R4ACR-EC4/.../...	02		1411862 NBC-R4AC- R4ACR-PN4/.../...
1411872 NBC-R4ACR- R4ACR-EC4/.../...	02		1411865 NBC-R4ACR- R4ACR-PN4/.../...
1411873 NBC-R4AC- F4AC-EC4/.../...	02		1418183 VS-PNRJ45- PNRJ45R-93B-0,3
1402498 VS-PNRJ45- PNRJ45R-93G-0,3	04		1418196 VS-PNRJ45R- PNRJ45R-93B-0,3
1402499 VS-PNRJ45R- PNRJ45R-93G-0,3	03		1418248 VS-PNRJ45- PNRJ45R-93B-1,0
1402505 VS-PNRJ45- PNRJ45R-93G-1,0	04		1418277 VS-PNRJ45- PNRJ45R-93B-2,0
1402508 VS-PNRJ45- PNRJ45R-93G-2,0	04		1409003 NBC- R4ACR/2,0-93B/R4ACR
1402509 VS-PNRJ45R- PNRJ45R-93G-2,0	03		1418413 VS-PNRJ45- PNRJ45-93B-0,3
1402510 VS-PNRJ45- PNRJ45-93G-0,3	03		1408968 NBC- R4AC/1,0-93B/R4AC
1408981 NBC- R4AC/1,0-93G/R4AC	03		1408969 NBC- R4AC/2,0-93B/R4AC
1408982 NBC- R4AC/2,0-93G/R4AC	03		1408970 NBC- R4AC/5,0-93B/R4AC
1408983 NBC- R4AC/5,0-93G/R4AC	03		1408971 NBC- R4AC/10,0-93B/R4AC
1408984 NBC- R4AC/10,0-93G/R4AC	03		1409002 NBC- R4ACR/1,0-93B/R4ACR
1409006 NBC- R4ACR/1,0-93G/R4ACR	03		1409003 NBC- R4ACR/2,0-93B/R4ACR
1409007 NBC- R4ACR/2,0-93G/R4ACR	03		1409004 NBC- R4ACR/5,0-93B/R4ACR
1409014 NBC- R4ACR/5,0-93G/R4ACR	03		1409005 NBC- R4ACR/10,0-93B/R4ACR

Item	Revision status		Substitute item
	Hardware/Firmware OLD	Hardware/ Firmware NEW	
1409015 NBC- R4ACR/10,0-93G/R4ACR	03		
1415304 NBC- R4AC/0,3-93H/R4AC	02		
1415305 NBC- R4AC/1,0-93H/R4AC	02		
1415306 NBC- R4AC/5,0-93H/R4AC	02		
1409740 NBC- R4AC/30,0-93G/R4ACR	03		
1409741 NBC- R4AC/50,0-93G/R4ACR	03		
1419142 VS-IP20- FPN-93G-LI/2,0	02		
1419145 VS-IP20- IP20-93G-LI/2,0	01		
1423234 NBC- R4AC/20,0-93G/R4AC D04	02		
1422863 NBC- R4AC/0,5-93G/R4AC	00		
1422864 NBC- R4AC/20,0-93G/R4AC	00		
1034986 VS-FSDBPS- OE-93G-LI/0,3 GN			