

Product Change Notification

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

1. ECR #: 193685 Notification #: 522 2. Date of Announcement: June 15, 2020

3. Series:

• UMPT - UMPT ASSEMBLY

4. Part #'s Affected


• UMPT-XX-XX.X-X-VT-XX-X-XX-X

5. Description of Change:

Update model from flat SM tail to grooved SM tails.

6. Method of Identifying Change

Visual inspection.



7. Reason for Change:

Modified contact tails by adding contour to increase solderable surface area and improve solder joint integrity. Revised contact tails passed standard qualification and interconnect processing tests.

8. Impact of Change on Form, Fit, or Function:

- Function Modified contact tails by adding contour to increase solderable surface area and improve solder joint integrity.
- 9. Projected Implementation Date: September 13, 2020

Disclaimer

Please review the change notification details listed above for specific information regarding the nature and timing of the change. While Samtec has taken precautions to ensure this change is not detrimental to your application, each application can be unique and therefore customers should consider the effect of the change on their specific application.

Samtec has taken efforts to ensure that all users of this product who have requested change notifications have been informed. However, you should assume that this is the only notification that will be sent and you, as the recipient, must determine how to communicate this information to your organization(s) and customer(s) as appropriate. If you wish to opt out of receiving Samtec Engineering Change Notification emails, please contact CustomerECN@samtec.com. Due to technical progress, specifications are subject to change without notification and it is recommended to provide an alternative contact when opting out.

Please contact Samtec at <u>CustomerECN@samtec.com</u> for any questions related to this change.