

## Product change notification (PCN)

<b>Title / short description</b>	FL-PP-RJ45... patch panels, optimized RJ45 jack
<b>Affected article category</b>	Industrial communication technology
<b>Change category</b>	Characteristics
<b>Change number</b>	CDN200010-00

### Purpose/objective of the change

Optimized RJ45 jack

### Detailed description of the change

The FL-PP-RJ45... patch panels will be supplied with an optimized RJ45 jack. The technical properties will remain unchanged. The devices are fully compatible with the predecessor versions.

### Identifying characteristics

The plastic inside the jack is black (previously: white)

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	-
<b>Effective date (EOP)</b>	2020-07-15	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	-		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

### Attachments

- CDN200010\_Front\_old.png
- CDN200010\_Front\_new.png
- Material\_list.csv
- PCN-CDN200010-00 Patch-Panel FL-PP-RJ45..., optimierte RJ45-Buchse\_DE
- PCN-CDN200010-00 FL-PP-RJ45... patch panels, optimized RJ45 jack\_EN

### Material list

Item	Article Type	Hardware old	Firmware new	Item	Substitute item Type
2901642	FL-PP-RJ45-SCC	07	08		
2901643	FL-PP-RJ45-SC	07	08		
2901645	FL-PP-RJ45-LSA	05	06		
2901646	FL-PP-RJ45/RJ45	06	07		
2903532	FL-PP-RJ45-SCC/SC041	02	03		