

**Issue Date:** November 01, 2021

Dear Valued Customer,

This PCN C0383 notice is to inform you of a product MOQ change affecting selected Littelfuse items.

***Description of the Change:***

To ensure timely fulfillment of product occurs, we will change the MOQ of our POWR-BLOK™ products to align with their standard pack.

***Reason for The Change:***

Due to an error during the annual updates, the standard pack was entered wrong for the POWR-BLOK™ family and to ensure deliveries can continue the MOQ will be aligned to standard pack as rework is not possible for this family.

***Effective Date of the Change:***

November 01, 2021

***What You Need to Do:***

Update existing and future POs to reflect the new MOQ quantity.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

*Francisco Gonzalez*

Associate Product Manager  
Commercial Vehicle Products