

Date : 02 Nov 2021

PRODUCT OBSOLESCENCE NOTICE

BI Technologies regrets to announce the end of life of the HM79-series. Please refer to the table below for suggested replacements in the HM79M-series.

EOL	Suggested Replacement	EOL	Suggested Replacement
HM79-201R0LFTR13	HM79M-201R0LFTR	HM79-60150LFTR13	HM79M-60150LFTR
HM79-204R7LFTR13	HM79M-204R7LFTR	HM79-60180LFTR13	N/A
HM79-206R8LFTR13	N/A	HM79-60220LFTR13	HM79M-60220LFTR
HM79-20100LFTR13	HM79M-20100LFTR	HM79-60270LFTR13	HM79M-60270LFTR
HM79-20120LFTR13	N/A	HM79-60330LFTR13	HM79M-60330LFTR
HM79-20150LFTR13	HM79M-20150LFTR	HM79-60390LFTR13	N/A
HM79-20180LFTR13	HM79M-20180LFTR	HM79-60470LFTR13	HM79M-60470LFTR
HM79-20220LFTR13	HM79M-20220LFTR	HM79-60560LFTR13	HM79M-60560LFTR
HM79-20270LFTR13	N/A	HM79-60680LFTR13	HM79M-60680LFTR
HM79-20330LFTR13	HM79M-20330LFTR	HM79-60820LFTR13	HM79M-60820LFTR
HM79-20390LFTR13	N/A	HM79-60101LFTR13	HM79M-60101LFTR
HM79-20470LFTR13	HM79M-20470LFTR	HM79-60121LFTR13	HM79M-60121LFTR
HM79-20560LFTR13	HM79M-20560LFTR	HM79-60151LFTR13	HM79M-60151LFTR
HM79-20680LFTR13	HM79M-20680LFTR	HM79-60181LFTR13	N/A
HM79-20820LFTR13	N/A	HM79-60221LFTR13	HM79M-60221LFTR
HM79-20101LFTR13	HM79M-20101LFTR	HM79-60271LFTR13	N/A
HM79-20121LFTR13	N/A	HM79-60331LFTR13	HM79M-60331LFTR
HM79-20151LFTR13	HM79M-20151LFTR	HM79-60391LFTR13	N/A
HM79-20181LFTR13	HM79M-20181LFTR	HM79-60471LFTR13	HM79M-60471LFTR
HM79-20221LFTR13	HM79M-20221LFTR	HM79-60561LFTR13	HM79M-60561LFTR
HM79-60100LFTR13	HM79M-60100LFTR	HM79-60681LFTR13	HM79M-60681LFTR
HM79-60120LFTR13	N/A	HM79-60821LFTR13	HM79M-60821LFTR

For more information, please contact your local BI Technologies sales representative.

Yours sincerely,

Raj Kumar Singaraju

Global Product Line Director, Magnetics
 TT Electronics