

## Product discontinuation notification (PDN)

**Title / short description** 30-Month Discontinuation - COMBICON Terminals 2 of 2  
**Affected article category** PCB terminal blocks and PCB connectors  
**Change category** Discontinuation  
**Change number** IAA250020-01  
**Reason for PCN/PDN Revision**

### Purpose/objective of the change

Discontinuation due to portfolio optimization

### Detailed description of the change

As part of our ongoing portfolio optimization, the listed articles will be discontinued from our product range. This decision was made after careful evaluation to ensure we continue providing the most innovative and effective solutions.

Please refer to the attached Excel sheet for initial replacement options that closely match the discontinued articles. For further coordination regarding replacement solutions, remaining stock, and last-time deliveries (LTD), please contact our sales department. Our sales team will be pleased to support you with any questions or requirements.

### Identifying characteristics

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	2028-01-31
<b>Effective date (EOP)</b>	-	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	2027-07-31		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

### Attachments

- PDN IAA250020 replacement options.xlsx
- Material\_list.csv
- PDN-IAA250020-01\_EN

### Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1993035	MKDSC 5/ 6-7,62 GY BDNZ2202856				
1993048	MKDSC 5/ 6-7,62 GY BDNZ2202857				
1709530	MKDSV 5/ 2-7,62 GY BD:L1,N				
1805038	MKDSV 5/ 2-7,62 GY BD:T1,T2				
1907131	MKDSV 5/ 2-7,62				
1453844	MKKDS 5/ 8-9,5 GY7032BDS/1-A/8				
1680556	MKKDS 5/ 8-9,52 GY7032				
1703355	MKKDS 5/12-9,5 BD:36-25,12-1				
1703356	MKKDS 5/12-9,5 BD:48-37,24-13				
1703357	MKKDS 5/12-9,5 BD:84-73,60-49				
1703358	MKKDS 5/12-9,5 BD:96-85,72-61				
1703359	MKKDS 5/2-9,5 BD:97-100				
1719015	MKKDS 5/ 2-9,5				
1719028	MKKDS 5/ 3-9,5				
1801146	MKKDS 5/ 2-9,5 BK				
1484015	MKKDS 5/ 8-9,5 GY7032BDS-A/8MQ				
1904105	MKKDS 5/ 3-9,5 BK				
1856168	MKDSP 50/ 1-17,5-FL				
1933011	KST-POF				
1706112	GRZ 2,5 V-EX				
1724628	GRZ 2,5-EX				
0706508	DFK-2,8-FRONT 2,5				
0706524	DFK/DP-2,8-FRONT 2,5				
0708315	DFK 4-PE				
0706605	DFK 5-9,5				
1932575	MKDSP 25/ 1-15,00-FL				
1176123	PLW 16-6/ 4-10 NW				
1287795	PLW 16-6/ 5-10 BDL1-PE				
1629643	PLW 16-6/ 5-10 BD:L1-PE				
1821067	PLW 16-6/ 3-10				
1821070	PLW 16-6/ 4-10				
1821083	PLW 16-6/ 5-10				